

DIAGONAL CURB RAMPS (NOT RECOMMENDED)