


1. Control line (Station Line or PGL)
2. Working point
3. Overall dimensioning
4. Working point dimensioning
5. Beam spacing dimensioning
6. Column spacing dimensioning
7. Cap widths dimensioning
8. Cap centerline located
9. Centerline of bearing located
10. Typical bearing seat
11. Skew angle

Fig. 4-4